

# **Kodak i600 Series Scanners Software Release Notes**

## **Version CD 4.6 Summary**

**Purpose of Release:** This release was created to add support for the Microsoft Windows 7 64bit operating system. The TWAIN driver and Firmware were not updated in this release.

**Date:** January 4<sup>th</sup>, 2011

### **Versions:**

TWAIN driver:	9.25.5
ISIS driver:	2.1.11004.5001
Scan Validation Tool:	6.10
Firmware:	4.03
STI driver:	1.3 (signed)
Color Tables:	2.0.4

### **New Features from CD 4.5:**

1. Add Windows 7 (64bit)

### **Improvements from CD 4.5:**

1. ISIS#31652 Corrected issue with retaining Automatic Color Detection values.

### **Supported Operating Systems:**

WINDOWS XP Pro  
WINDOWS Vista (32bit)  
WINDOWS 7 (32 and 64bit)

## **Version CD 4.5 Summary**

**Purpose of Release:** This release (CSM4) was created to add support for Windows 7 (32bit only) Operating System. This release does not support the Windows 7 64bit version. The TWAIN driver and Firmware were not updated in this release. The ISIS driver was updated to support Windows 7 32bit.

**Date:** June 18<sup>st</sup>, 2010

### **Versions:**

TWAIN driver:	9.25.5
ISIS driver:	2.0.11002.26005
Scan Validation Tool:	6.10
Firmware:	4.03
STI driver:	1.3 (signed)
Color Tables:	2.0.4

### **New Features from CD 4.2:**

2. Add Windows 7 (32bit only)

### **Improvements from CD 4.2:**

2. Setup: Improved Web Installer to no longer be dependent on autorun.inf to prevent "Operating System not supported" messages during installation.

## Version CD 4.4 Summary

**Purpose of Release:** This release was created to correct a problem with the ISIS driver not setting the elevator mode correctly and to update the TWAIN driver to the version 9.x level.

**Note:** On 5/16/2008 Kofax released an update to their VirtualReScan(VRS) v4.2 product to enable support of this version (9.x) of the Kodak TWAIN driver. All Kofax VRS customers must have VRS 4.2 and the *Kodaki600Update.exe* update installed to successfully use this driver.

**Date:** January 10<sup>th</sup>, 2008

### Versions:

TWAIN driver:	9.25.5
ISIS driver:	2.0.10711.12001
Scan Validation Tool:	6.10
Firmware:	4.03
STI driver:	1.3 (signed)
Color Tables:	2.0.4

### New Features from CD 4.2:

3. (none)

### Improvements from CD 4.2:

1. ISIS: Corrected problem with elevator not descending.
2. ISIS: Corrected multifeed detection by length configuration problem.
3. ISIS: Corrected rear camera configuration issues.
4. TWAIN: Corrected problem with running driver on a Czechoslovakian Windows PC.